

How to use Zerust[®] ICT[®] packaging material.

CORRECT




All packs must be tightly closed. Seal packs by heat sealing or applying waterproof tape.

WRONG




CORRECT




When packing, the temperature of the parts being packaged must be the same as the current room temperature.

WRONG



CORRECT




Insert additional Zerust[®] materials as interleave to provide additional protection in tightly packed areas

WRONG




CORRECT




Avoid direct contact of metal with wood, paper or cardboard! Cover intermediate layers with Zerust[®]!

WRONG




CORRECT




Pack only clean and dry parts.

WRONG



CORRECT



Always wear clean and dry gloves before handling metal parts.

WRONG

